

ACURITE®

Instructions For Use:

Select Temperature Units: Press and release the "F/C" button located on the back of the thermometer.

Select Location: Press the \blacklozenge button to select the desired mode (FRIDGE or FREEZER). \blacktriangle will appear when readings are outside of preset safe zones.

Clear Records: The thermometer records high and low temperature records, recorded since the thermometer was first powered on or since the records were cleared. Press and hold the \blacklozenge button for 3 seconds to clear high and low records. Dashes display to confirm you have cleared the records.

Instrucciones de uso:

Seleccione las unidades de temperatura: Presione y suelte el botón "F/C" ubicado en la parte posterior del termómetro.

Seleccione la ubicación: Presione el botón \blacklozenge para seleccionar el modo deseado (FRIDGE o FREEZER) (REFRIGERADOR o CONGELADOR). \blacktriangle aparecerá cuando las lecturas estén fuera de los límites seguros predeterminados.

Borrar registros: El termómetro registra las temperaturas máximas y mínimas históricas, registradas desde que el termómetro fue encendido por primera vez o desde que los registros fueron borrados. Presione y sostenga el botón \blacklozenge durante 3 segundos para borrar las temperaturas máximas y mínimas históricas. Una vez que los registros se hayan borrado, aparecerán unas rayas/guiones.

WARNING:
DO NOT place on or near hot surfaces.
DO NOT wash in dishwasher.
DO NOT submerge in water.

ADVERTENCIA:
NO lo coloque en superficies caliente ni cerca de éstas. NO se lave en lavavajillas. No sumerja en agua.

Care Instructions:

Wipe with damp cloth.

Instrucciones de lavado: Límpielo con un paño húmedo.

DO NOT mix old and new batteries or types of batteries (alkaline/standard). DO NOT use rechargeable batteries.

No mezcle baterías viejas y nuevas o tipos de baterías (alcalina/estándar). No use baterías recargables.

Product Facts

Batteries: 2 x CR2032 (included)

Measurement Ranges

Temperature: -40°F to 99.9°F
-40°C to 37.7°C

Preset Safe Zones

Refrigerator: 33°F to 40°F
0.6°C to 4.4°C

Freezer: -22°F to 0°F
-30°C to -17.8°C

AcuRite uses patented technology.

Visit www.AcuRite.com/patents for details.

REV1222 AcuRite is a registered trademark of Chaney Instrument Co. 965 Wells St. Lake Geneva, WI 53147

00521W



MADE IN CHINA • HECHO EN CHINA

877-221-1252

www.AcuRite.com



LIMITED 1-YEAR WARRANTY

Register your product on:
www.AcuRite.com